

# PULL OUT TORQUE CURVE OF 42HT51-3003S

Microstep : 1000  
Current :3A

AC 220V

